

EXCERPT FROM THE MINUTES OF THE REGULAR SESSION OF THE SANGGUNIANG BAYAN HELD AT THE SB SESSION ROOM, MUNICIPAL HALL ON TUESDAY, OCTOBER 18, 2016

Present: Vice-Mayor William P. Cura, Presiding Officer
Councilor Johnny M. Sales
Councilor Ernesto M. Salting
Councilor Alvin Dale M. Sibal
Councilor Danilo L. Lugtu
Councilor Reynaldo L. Pangilinan, Sr.
Councilor Noel S. Rivera
Councilor Ariel S. Alimurong
Councilor Ernesto P. Go
Councilor Jose M. Salting, Jr. President Liga ng mga Barangay

Absent: No one

RESOLUTION NO. 058, SERIES OF 2016

REQUESTING THE OFFICE OF THE MUNICIPAL ENGINEER TO CONDUCT AN IMMEDIATE INSPECTION OF THE PANDAN AND MASCUP BRIDGES IN BARANGAY ANUPUL

WHEREAS, it has been brought to the attention of the Sangguniang Bayan that the approach of the two bridges in Anupul – namely, Pandan bridge and Mascup bridge have been eroded and are at risk of collapsing in the event that there is an avalanche of floodwater in the area;

WHEREAS, an immediate repair of the aforementioned bridges is necessary in order to prevent any untoward incident or accident to motorists;

NOW THEREFORE, on motion of Councilor Reynaldo L. Pangilinan, Sr. duly seconded by Councilor Jose M. Salting, Jr.:

RESOLVED, to request the Office of the Municipal Engineer to conduct an immediate inspection of the Pandan and Mascup bridges in Barangay Anupul, this Municipality.

CARRIED.

Certified correct:

MARLENE C. PANGILINAN
SB Secretary

Attested:

WILLIAM P. CURA
Municipal Vice-Mayor & Presiding Officer